

Fig. 1A




Fig. 1B




Fig. 2




Fig. 3A




Fig. 3B

(1) Sensor measurement with small standard deviation, σ_p .

(2) Sensor measurement with large standard deviation, σ_p .




Fig. 3C





Fig. 3D

(1) Sensor measurement with small standard deviation, σ_p .



(2) Sensor measurement with large standard deviation, σ_p .




Fig. 3E

Fig. 3F




Fig. 4

